

土壤汚染詳細調査結果(鉛及びその化合物)

| 単位 区画 | 地番 | 採取深度 (GL-m) | 溶出量 (mg/L) | 単位 区画 | 地番 | 採取深度 (GL-m) | 溶出量 (mg/L) | 単位 区画 | 地番 | 採取深度 (GL-m) | 溶出量 (mg/L) |
|----------|--------------------------------------|----------------|---------------|----------|-----------------------------|----------------|---------------|----------|-----------------------------|----------------|---------------|
| A3-7 | 大阪市東淀川 区下新庄五丁 目475、476 の各一部 | 0.0~0.5 | 0.038 | B2-6 | 大阪市東淀川 区下新庄五丁 目475の一部 | 0.0~0.5 | 0.015 | B3-9 | 大阪市東淀川 区下新庄五丁 目475の一部 | 0.0~0.5 | 0.040 |
| | | 1.0 | 0.040 | | | 1.0 | 0.016 | | | 1.0 | 0.019 |
| | | 2.0 | 0.008 | | | 2.0 | <0.005 | | | 2.0 | <0.005 |
| | | 3.0 | 0.014 | | | 3.0 | 0.016 | | | 3.0 | 0.018 |
| | | 3.5 | <0.005 | | | 3.5 | 0.005 | | | 3.5 | 0.006 |
| | | 4.0 | 0.010 | | | 4.0 | 0.008 | | | 4.0 | 0.010 |
| | | 5.0 | 0.008 | | | 5.0 | 0.005 | | | 5.0 | <0.005 |
| | | 6.0 | 0.006 | | | 6.0 | <0.005 | | | 6.0 | <0.005 |
| | | 7.0 | 0.009 | | | 7.0 | <0.005 | | | 7.0 | 0.005 |
| | | 8.0 | <0.005 | | | 8.0 | <0.005 | | | 8.0 | <0.005 |
| | | 9.0 | <0.005 | | | 9.0 | <0.005 | | | 9.0 | <0.005 |
| 10.0 | <0.005 | 10.0 | <0.005 | 10.0 | <0.005 | | | | | | |
| A4-1 | 大阪市東淀川 区下新庄五丁 目475、476 の各一部 | 0.0~0.5 | 0.025 | B2-9 | 大阪市東淀川 区下新庄五丁 目475の一部 | 0.0~0.5 | 0.042 | B4-3 | 大阪市東淀川 区下新庄五丁 目475の一部 | 0.0~0.5 | 0.033 |
| | | 1.0 | 0.019 | | | 1.0 | 0.027 | | | 1.0 | 0.029 |
| | | 2.0 | 0.006 | | | 1.5 | <0.005 | | | 2.0 | 0.007 |
| | | 3.0 | 0.041 | | | 2.0 | <0.005 | | | 3.0 | 0.025 |
| | | 3.5 | <0.005 | | | 3.0 | 0.008 | | | 3.5 | 0.006 |
| | | 4.0 | 0.008 | | | 4.0 | 0.008 | | | 4.0 | 0.010 |
| | | 5.0 | <0.005 | | | 5.0 | <0.005 | | | 5.0 | 0.005 |
| | | 6.0 | 0.006 | | | 6.0 | <0.005 | | | 6.0 | <0.005 |
| | | 7.0 | 0.010 | | | 7.0 | <0.005 | | | 7.0 | <0.005 |
| | | 8.0 | <0.005 | | | 8.0 | <0.005 | | | 8.0 | <0.005 |
| | | 9.0 | 0.006 | | | 9.0 | <0.005 | | | 9.0 | <0.005 |
| 10.0 | 0.009 | 10.0 | <0.005 | 10.0 | <0.005 | | | | | | |
| A4-4 | 大阪市東淀川 区下新庄五丁 目475、476 の各一部 | 0.0~0.5 | 0.018 | B3-3 | 大阪市東淀川 区下新庄五丁 目475の一部 | 0.0~0.5 | 0.022 | B4-6 | 大阪市東淀川 区下新庄五丁 目475の一部 | 0.0~0.5 | 0.030 |
| | | 1.0 | 0.022 | | | 1.0 | 0.012 | | | 1.0 | 0.024 |
| | | 1.5 | 0.011 | | | 2.0 | 0.007 | | | 1.5 | <0.005 |
| | | 2.0 | 0.005 | | | 3.0 | 0.016 | | | 2.0 | 0.005 |
| | | 3.0 | 0.006 | | | 3.5 | <0.005 | | | 3.0 | <0.005 |
| | | 4.0 | 0.005 | | | 4.0 | <0.005 | | | 4.0 | <0.005 |
| | | 5.0 | 0.009 | | | 5.0 | <0.005 | | | 5.0 | <0.005 |
| | | 6.0 | 0.009 | | | 6.0 | <0.005 | | | 6.0 | 0.005 |
| | | 7.0 | <0.005 | | | 7.0 | <0.005 | | | 7.0 | <0.005 |
| | | 8.0 | <0.005 | | | 8.0 | <0.005 | | | 8.0 | <0.005 |
| | | 9.0 | 0.005 | | | 9.0 | 0.008 | | | 9.0 | 0.008 |
| 10.0 | 0.006 | 10.0 | 0.008 | 10.0 | 0.010 | | | | | | |
| B2-3 | 大阪市東淀川 区下新庄五丁 目475の一部 | 0.0~0.5 | 0.025 | B3-6 | 大阪市東淀川 区下新庄五丁 目475の一部 | 0.0~0.5 | 0.054 | | | | |
| | | 0.6 | 0.007 | | | 1.0 | 0.018 | | | | |
| | | 1.0 | 0.006 | | | 1.5 | <0.005 | | | | |
| | | 2.0 | 0.006 | | | 2.0 | <0.005 | | | | |
| | | 3.0 | 0.005 | | | 3.0 | 0.006 | | | | |
| | | 4.0 | 0.007 | | | 4.0 | <0.005 | | | | |
| | | 5.0 | <0.005 | | | 5.0 | 0.005 | | | | |
| | | 6.0 | <0.005 | | | 6.0 | <0.005 | | | | |
| | | 7.0 | <0.005 | | | 7.0 | 0.005 | | | | |
| | | 8.0 | <0.005 | | | 8.0 | <0.005 | | | | |
| | | 9.0 | <0.005 | | | 9.0 | <0.005 | | | | |
| 10.0 | <0.005 | 10.0 | <0.005 | | | | | | | | |

注) 網掛けは、基準不適合を示す。