

土壤汚染詳細調査結果(鉛及びその化合物)(溶出量)

③

単位 区画	地番	採取深度 (GL-m)	溶出量 (mg/L)	単位 区画	地番	採取深度 (GL-m)	溶出量 (mg/L)	単位 区画	地番	採取深度 (GL-m)	溶出量 (mg/L)
A1-7	大阪市東淀川区 東淡路二丁目 194-1の一部	0~0.5	0.015	A6-7	大阪市東淀川区 東淡路二丁目 194-1の一部	0~0.5	0.020	A9-7	大阪市東淀川区 東淡路二丁目 197、198、199 の各一部	0~0.5	0.011
		0.6	0.017			1.0	0.044			0.6	0.019
		1.0	0.009			1.5	<0.005			1.0	0.007
		2.0	0.005			2.0	<0.005			2.0	0.009
		3.0	<0.005			3.0	<0.005			3.0	<0.005
		4.0	<0.005			4.0	<0.005			4.0	0.007
		5.0	<0.005			5.0	<0.005			5.0	0.009
		6.0	<0.005			6.0	<0.005				
		7.0	<0.005			7.0	<0.005				
		8.0	<0.005			8.0	<0.005				
		9.0	<0.005			9.0	<0.005				
10.0	<0.005	10.0	<0.005								
A2-4	大阪市東淀川区 東淡路二丁目 194-1の一部	0~0.5	0.026	A7-1	大阪市東淀川区 東淡路二丁目 194-1の一部	0~0.5	0.012	A10-1	大阪市東淀川区 東淡路二丁目 197、198、199 の各一部	0~0.5	0.075
		0.6	<0.005			0.6	0.007			1.0	0.015
		1.0	0.005			1.0	<0.005			1.5	<0.005
		2.0	0.010			2.0	<0.005			2.0	<0.005
		3.0	<0.005			3.0	0.008			3.0	<0.005
		4.0	<0.005			4.0	<0.005			4.0	0.010
		5.0	<0.005			5.0	<0.005			5.0	<0.005
		6.0	<0.005			6.0	<0.005			6.0	<0.005
		7.0	<0.005			7.0	<0.005			7.0	<0.005
		8.0	<0.005			8.0	<0.005			8.0	<0.005
		9.0	<0.005			9.0	<0.005			9.0	<0.005
10.0	<0.005	10.0	<0.005	10.0	<0.005						
A4-1	大阪市東淀川区 東淡路二丁目 194-1の一部	0~0.5	0.011	A7-4	大阪市東淀川区 東淡路二丁目 171-2、194-1、 197、198、199 の各一部	0~0.5	0.027	A10-7	大阪市東淀川区 柴島一丁目 832-1、832-3 の各一部	0~0.5	0.023
		0.6	0.032			1.0	0.039			0.6	0.043
		1.0	<0.005			1.5	<0.005			1.0	<0.005
		2.0	0.007			2.0	0.005			2.0	<0.005
		3.0	<0.005			3.0	<0.005			3.0	<0.005
		4.0	<0.005			4.0	<0.005			4.0	<0.005
		5.0	<0.005			5.0	<0.005			5.0	<0.005
		6.0	<0.005			6.0	<0.005			6.0	<0.005
		7.0	<0.005			7.0	<0.005			7.0	<0.005
		8.0	<0.005			8.0	<0.005			8.0	<0.005
		9.0	<0.005			9.0	<0.005			9.0	<0.005
10.0	<0.005	10.0	<0.005	10.0	<0.005						
A5-1	大阪市東淀川区 東淡路二丁目 194-1の一部	0~0.5	0.019	A7-7	大阪市東淀川区 東淡路二丁目 197、198、199 の各一部	0~0.5	0.031	A11-1	大阪市東淀川区 柴島一丁目 832-1、832-3 の各一部	0~0.5	0.031
		1	0.013			1.0	0.020			1.0	0.011
		1.5	<0.005			2.0	0.016			1.5	<0.005
		2.0	<0.005			2.5	<0.005			2.0	0.009
		3.0	<0.005			3.0	<0.005			3.0	0.005
		4.0	<0.005			4.0	<0.005			4.0	<0.005
		5.0	<0.005			5.0	<0.005			5.0	<0.005
		6.0	<0.005			6.0	<0.005				
		7.0	<0.005			7.0	<0.005				
		8.0	<0.005			8.0	<0.005				
		9.0	<0.005			9.0	<0.005				
10.0	<0.005	10.0	<0.005								
A6-4	大阪市東淀川区 東淡路二丁目 194-1の一部	0~0.5	0.024	A8-7	大阪市東淀川区 東淡路二丁目 197、198、199 の各一部	0~0.5	0.021	A11-4	大阪市東淀川区 柴島一丁目 777-1、777-2、 832-1、832-3 の各一部	0~0.5	0.025
		0.6	0.006			1.0	0.055			1.0	0.013
		1.0	<0.005			1.5	<0.005			1.5	<0.005
		2.0	<0.005			2.0	0.010			2.0	<0.005
		3.0	<0.005			3.0	<0.005			3.0	<0.005
		4.0	<0.005			4.0	<0.005			4.0	<0.005
		5.0	<0.005			5.0	<0.005			5.0	<0.005
		6.0	<0.005			6.0	<0.005			6.0	<0.005
		7.0	<0.005			7.0	<0.005			7.0	<0.005
		8.0	<0.005			8.0	<0.005			8.0	<0.005
		9.0	<0.005			9.0	<0.005			9.0	<0.005
10.0	<0.005	10.0	<0.005	10.0	<0.005						
A6-4	大阪市東淀川区 東淡路二丁目 194-1の一部	0~0.5	0.024	A9-4	大阪市東淀川区 東淡路二丁目 197、198、199 の各一部	0~0.5	0.024	A11-7	大阪市東淀川区 柴島一丁目 777-1、777-2、 832-3 の各一部	0~0.5	0.025
		0.6	0.006			1.0	0.017			0.6	0.017
		1.0	<0.005			1.5	0.006			1.0	<0.005
		2.0	<0.005			2.0	0.005			2.0	<0.005
		3.0	0.010			3.0	<0.005			3.0	<0.005
		4.0	<0.005			4.0	<0.005			4.0	<0.005
		5.0	0.009			5.0	<0.005			5.0	<0.005
						6.0	<0.005				
						7.0	<0.005				
						8.0	<0.005				
						9.0	<0.005				
		10.0	<0.005								
A6-4	大阪市東淀川区 東淡路二丁目 194-1の一部	0~0.5	0.024	A9-4	大阪市東淀川区 東淡路二丁目 197、198、199 の各一部	0~0.5	0.024	A12-4	大阪市東淀川区 柴島一丁目 777-1、777-2、 832-3 の各一部	0~0.5	0.018
		0.6	0.006			0.6	0.008				
		1.0	<0.005			1.0	<0.005				
		2.0	<0.005			2.0	<0.005				
		3.0	<0.005			3.0	<0.005				
		4.0	<0.005			4.0	<0.005				
5.0	<0.005	5.0	<0.005								

注) 網掛けは、基準不適合を示す。

土壤汚染詳細調査結果(鉛及びその化合物)(溶出量)

③

単位 区画	地番	採取深度 (GL-m)	溶出量 (mg/L)	単位 区画	地番	採取深度 (GL-m)	溶出量 (mg/L)	単位 区画	地番	採取深度 (GL-m)	溶出量 (mg/L)				
A12-7	大阪市東淀川区 柴島一丁目 777-1、777-2、 832-3 の各一部	0~0.5	0.014	A15-7	大阪市東淀川区 柴島一丁目 777-1、777-2 の各一部	0~0.5	0.025	A19-1	大阪市東淀川区 柴島一丁目 777-1、777-2 の各一部	0~0.5	0.024				
		1.0	0.078			0.6	0.010			0.6	<0.005				
		2.0	0.045			1.0	<0.005			1.0	<0.005				
		2.5	<0.005			2.0	<0.005			2.0	0.006				
		3.0	0.010			3.0	<0.005			3.0	<0.005				
		4.0	<0.005			4.0	<0.005			4.0	<0.005				
		5.0	<0.005			5.0	<0.005			5.0	<0.005				
		6.0	<0.005			6.0	0.008			6.0	0.005				
		7.0	<0.005			7.0	<0.005			7.0	<0.005				
		8.0	<0.005			8.0	<0.005			8.0	<0.005				
		9.0	<0.005			9.0	<0.005			9.0	<0.005				
10.0	<0.005	10.0	<0.005	10.0	<0.005										
A13-1	大阪市東淀川区 柴島一丁目 777-1、777-2、 832-3 の各一部	0~0.5	0.011	A16-4	大阪市東淀川区 柴島一丁目 777-1、777-2 の各一部	0~0.5	0.023	A19-7	大阪市東淀川区 柴島一丁目 777-1、777-2 の各一部	0~0.5	0.028				
		0.6	0.006			0.6	<0.005			0.6	0.011				
		1.0	<0.005			1.0	<0.005			1.0	0.005				
		2.0	<0.005			2.0	<0.005			2.0	<0.005				
		3.0	<0.005			3.0	<0.005			3.0	<0.005				
		4.0	<0.005			4.0	<0.005			4.0	<0.005				
5.0	<0.005	5.0	<0.005			5.0	0.005								
A13-4	大阪市東淀川区 柴島一丁目 777-1、777-2 の各一部	0~0.5	0.021			6.0	<0.005			6.0	<0.005	6.0	<0.005	6.0	<0.005
		0.6	<0.005			7.0	<0.005			7.0	<0.005	7.0	<0.005	7.0	<0.005
		1.0	<0.005			8.0	<0.005			8.0	<0.005	8.0	<0.005	8.0	<0.005
		2.0	<0.005	9.0	<0.005	9.0	<0.005	9.0	<0.005	9.0	<0.005				
		3.0	<0.005	10.0	<0.005	10.0	<0.005	10.0	<0.005	10.0	<0.005				
		4.0	<0.005	A17-1	大阪市東淀川区 柴島一丁目 777-1、777-2 の各一部	0~0.5	0.043	A20-1	大阪市東淀川区 柴島一丁目 777-1、777-2 の各一部	0~0.5	0.025				
		5.0	<0.005			0.6	<0.005			0.6	<0.005				
		6.0	<0.005			1.0	<0.005			1.0	<0.005				
		7.0	<0.005			2.0	<0.005			2.0	<0.005				
		8.0	<0.005			3.0	<0.005			3.0	<0.005				
9.0	<0.005	4.0	<0.005			4.0	<0.005								
10.0	<0.005	5.0	<0.005			5.0	0.009								
A14-1	大阪市東淀川区 柴島一丁目 777-1、777-2 の各一部	0~0.5	0.012			6.0	<0.005			A20-4	大阪市東淀川区 柴島一丁目 777-1、777-2 の各一部	0~0.5	0.024		
		0.6	0.005			7.0	<0.005					1.0	0.026		
		1.0	<0.005			8.0	<0.005					1.5	0.005		
		2.0	<0.005	9.0	<0.005	2.0	<0.005								
		3.0	0.010	10.0	<0.005	3.0	<0.005								
		4.0	0.006	A17-7	大阪市東淀川区 柴島一丁目 777-1、777-2 の各一部	0~0.5	0.026	4.0	<0.005						
		5.0	<0.005			0.6	<0.005	5.0	<0.005						
		6.0	<0.005			1.0	<0.005	6.0	<0.005						
		7.0	<0.005			2.0	<0.005	7.0	<0.005						
		8.0	<0.005			3.0	<0.005	8.0	<0.005						
9.0	<0.005	4.0	<0.005			8.0	<0.005								
10.0	<0.005	5.0	<0.005			9.0	<0.005								
A14-7	大阪市東淀川区 柴島一丁目 777-1、777-2 の各一部	0~0.5	0.015			6.0	<0.005	A20-7	大阪市東淀川区 柴島一丁目 777-1、777-2 の各一部	0~0.5	0.014				
		0.6	<0.005			7.0	<0.005			0.6	<0.005				
		1.0	<0.005			8.0	<0.005			1.0	<0.005				
		2.0	<0.005	9.0	<0.005	2.0	<0.005								
		3.0	<0.005	10.0	<0.005	3.0	<0.005								
		4.0	<0.005	A18-4	大阪市東淀川区 柴島一丁目 777-1、777-2 の各一部	0~0.5	0.022			4.0	<0.005				
		5.0	0.006			0.6	<0.005			5.0	<0.005				
		6.0	<0.005			1.0	<0.005			6.0	<0.005				
		7.0	<0.005			2.0	<0.005			7.0	0.010				
		8.0	<0.005			3.0	<0.005			8.0	<0.005				
		9.0	<0.005			4.0	<0.005			9.0	<0.005				
10.0	<0.005	5.0	0.005			10.0	<0.005								
		6.0	0.006			A21-1	大阪市東淀川区 柴島一丁目 777-1、777-2 の各一部	0~0.5	0.018						
		7.0	0.005					1.0	0.013						
		8.0	<0.005					1.5	0.008						
		9.0	<0.005	2.0	<0.005										
		10.0	<0.005	3.0	0.005										
				4.0	<0.005										
				5.0	<0.005										
				6.0	<0.005										
				7.0	0.010										
				8.0	<0.005										
				9.0	<0.005										
				10.0	<0.005										

注) 網掛けは、基準不適合を示す。

土壤汚染詳細調査結果(鉛及びその化合物)(溶出量)

単位 区画	地 番	採取深度 (GL-m)	溶出量 (mg/L)
A21-4	大阪市東淀川区 柴島一丁目 777-1、777-2 の各一部	0~0.5	0.022
		0.6	<0.005
		1.0	0.006
		2.0	<0.005
		3.0	<0.005
		4.0	<0.005
A21-7	大阪市東淀川区 柴島一丁目 777-1、777-2 の各一部	5.0	0.010
		0~0.5	0.034
		1.0	0.012
		2.0	0.040
		2.5	0.006
		3.0	0.007
		4.0	<0.005
		5.0	0.009
		6.0	0.005
		7.0	<0.005
		8.0	<0.005
9.0	<0.005		
A23-1	大阪市東淀川区 柴島一丁目 778-1の一部	10.0	<0.005
		0~0.5	0.055
		0.6	0.020
		1.0	0.010
		2.0	<0.005
		3.0	<0.005
		4.0	<0.005
		5.0	<0.005
		6.0	<0.005
		7.0	<0.005
		8.0	<0.005
9.0	<0.005		

注)網掛けは、基準不適合を示す。