

土壤汚染詳細調査結果(鉛及びその化合物)(溶出量)

単位 区画	地 番	採取深度 (GL-m)	溶出量 (mg/L)	単位 区画	地 番	採取深度 (GL-m)	溶出量 (mg/L)	単位 区画	地 番	採取深度 (GL-m)	溶出量 (mg/L)
A2-1 (A1-7)	大阪市東淀川区 東淡路二丁目 115-4の一部、 柴島一丁目 115-3 の一部	0~0.5	0.038	A5-2	大阪市東淀川区 柴島三丁目 110-2、110-3 の各一部	0~0.5	0.050	A10-8	大阪市東淀川区 柴島三丁目 110-2、110-5 の各一部	0~0.5	0.019
		0.6	<0.005			1.0	0.012			0.6	<0.005
		1.0	<0.005			2.0	0.011			1.0	<0.005
		2.0	<0.005			2.5	0.010			2.0	<0.005
		3.0	0.005			3.0	<0.005			3.0	0.010
		4.0	<0.005			4.0	<0.005			4.0	<0.005
		5.0	<0.005			5.0	<0.005			5.0	0.005
		6.0	<0.005			6.0	<0.005			6.0	<0.005
		7.0	<0.005			7.0	<0.005			7.0	<0.005
		8.0	<0.005			8.0	<0.005			8.0	<0.005
9.0	<0.005	9.0	<0.005	9.0	<0.005						
10.0	<0.005	10.0	<0.005	10.0	<0.005						
A2-7	大阪市東淀川区 柴島一丁目 110-1の一部、 柴島三丁目 110-2、110-3 の各一部	0~0.5	0.065	A7-2	大阪市東淀川区 柴島三丁目 110-2、110-4、 110-6 の各一部	0~0.5	0.022	A13-3	大阪市東淀川区 柴島三丁目 110-2、110-5 の各一部	0~0.5	0.023
		0.6	<0.005			1.0	0.036			0.6	0.032
		1.0	<0.005			2.0	0.012			1.0	<0.005
		2.0	0.010			2.5	0.007			2.0	<0.005
		3.0	0.010			3.0	<0.005			3.0	<0.005
		4.0	<0.005			4.0	<0.005			4.0	<0.005
		5.0	<0.005			5.0	<0.005			5.0	<0.005
		6.0	<0.005			6.0	<0.005			6.0	<0.005
		7.0	<0.005			7.0	<0.005			7.0	<0.005
		8.0	<0.005			8.0	<0.005			8.0	<0.005
9.0	<0.005	9.0	<0.005	9.0	<0.005						
10.0	<0.005	10.0	<0.005	10.0	<0.005						
A3-5 (A3-2)	大阪市東淀川区 柴島三丁目 110-3の一部	0~0.5	0.023	A7-5	大阪市東淀川区 柴島三丁目 110-2、110-4 の各一部	0~0.5	0.019	A14-3	大阪市東淀川区 柴島三丁目 292-2の一部	0~0.5	0.043
		1.0	0.009			0.6	0.019			0.6	0.007
		2.0	0.020			1.0	<0.005			1.0	<0.005
		2.5	0.008			2.0	0.005			2.0	<0.005
		3.0	<0.005			3.0	0.005			3.0	<0.005
		4.0	<0.005			4.0	<0.005			4.0	<0.005
		5.0	0.008			5.0	<0.005			5.0	<0.005
		6.0	0.010			6.0	<0.005			6.0	<0.005
		7.0	<0.005			7.0	<0.005			7.0	<0.005
		8.0	<0.005			8.0	<0.005			8.0	<0.005
9.0	<0.005	9.0	<0.005	9.0	<0.005						
10.0	<0.005	10.0	<0.005	10.0	<0.005						
A3-8	大阪市東淀川区 柴島三丁目 110-2、110-3 の各一部	0~0.5	0.042	A7-8	大阪市東淀川区 柴島三丁目 110-2、110-4 の各一部	0~0.5	0.011	A15-6	大阪市東淀川区 柴島三丁目 243の一部	0~0.5	0.055
		1.0	0.006			1.0	0.016			0.6	0.032
		2.0	0.019			2.0	0.039			1.0	<0.005
		2.5	<0.005			3.0	0.038			2.0	<0.005
		3.0	0.006			3.5	0.071			3.0	<0.005
		4.0	<0.005			4.0	0.010			4.0	<0.005
		5.0	<0.005			5.0	0.010			5.0	0.005
		6.0	<0.005			6.0	<0.005			6.0	0.005
		7.0	<0.005			7.0	<0.005			7.0	<0.005
		8.0	<0.005			8.0	<0.005			8.0	<0.005
9.0	<0.005	9.0	<0.005	9.0	<0.005						
10.0	<0.005	10.0	<0.005	10.0	<0.005						
A4-1	大阪市東淀川区 柴島三丁目 110-2、110-3 の各一部	0~0.5	0.012	A10-2 (A9-5) (A9-8)	大阪市東淀川区 柴島三丁目 110-2、110-4、 110-5 の各一部	0~0.5	0.027	A16-9	大阪市東淀川区 柴島三丁目 267-4の一部	0~0.5	0.034
		1.0	0.012			1.0	<0.005			0.6	0.025
		1.5	0.027			2.0	0.013			1.0	<0.005
		2.0	0.010			2.5	0.043			2.0	<0.005
		3.0	<0.005			3.0	0.005			3.0	<0.005
		4.0	<0.005			4.0	0.008			4.0	<0.005
		5.0	<0.005			5.0	0.010			5.0	<0.005
		6.0	<0.005			6.0	<0.005			6.0	0.007
7.0	<0.005	7.0	<0.005	7.0	<0.005						
A4-8	大阪市東淀川区 柴島三丁目 110-2、110-3 の各一部	0~0.5	0.023	A10-5	大阪市東淀川区 柴島三丁目 110-2、110-5 の各一部	0~0.5	0.032				
		1.0	0.037			0.6	<0.005				
		1.5	<0.005			1.0	<0.005				
		2.0	<0.005			1.5	0.005				
		3.0	<0.005			2.0	0.006				
		4.0	<0.005			2.5	0.009				
		5.0	<0.005			3.0	0.005				
		6.0	<0.005			3.5	<0.005				
7.0	<0.005	4.0	<0.005								
		5.0	<0.005								
		6.0	<0.005								
		7.0	<0.005								

注) 網掛けは、基準不適合を示す。

土壤汚染詳細調査結果(鉛及びその化合物)(含有量)

単 位 区 画	地 番	採取深度 (GL-m)	含有量 (mg/kg)	単 位 区 画	地 番	採取深度 (GL-m)	含有量 (mg/kg)
A2-1	大阪市東淀川区 東淡路二丁目 115-4の一部、 柴島一丁目 115-3の各一部	0~0.5	170	A5-2	大阪市東淀川区 柴島三丁目 110-2、110-3 の各一部	0~0.5	290
		0.6	13			1.0	18
		1.0	27			2.0	16
		2.0	26			2.5	11
		3.0	11			3.0	5
		4.0	11			4.0	1
		5.0	4			5.0	1
		6.0	3			6.0	1
		7.0	2			7.0	<1
		8.0	1			8.0	<1
		9.0	1			9.0	<1
10.0	<1	10.0	<1				
A2-7	大阪市東淀川区 柴島一丁目 110-1の一部、 柴島三丁目 110-2、110-3 の各一部	0~0.5	330	A13-3	大阪市東淀川区 柴島三丁目1 10-2、110-5 の各一部	0~0.5	180
		0.6	52			0.6	25
		1.0	42			1.0	19
		2.0	17			2.0	4
		3.0	15			3.0	1
		4.0	2			4.0	1
		5.0	1			5.0	<1
		6.0	1			6.0	<1
		7.0	1			7.0	<1
		8.0	<1			8.0	<1
		9.0	<1			9.0	<1
10.0	1	10.0	<1				
A3-5	大阪市東淀川区 柴島三丁目 110-3の一部	0~0.5	190				
		1.0	12				
		2.0	13				
		2.5	4				
		3.0	3				
		4.0	1				
		5.0	3				
		6.0	3				
		7.0	1				
		8.0	1				
		9.0	1				
10.0	1						
A3-8	大阪市東淀川区 柴島三丁目 110-2、110-3 の各一部	0~0.5	190				
		1.0	15				
		2.0	18				
		2.5	7				
		3.0	2				
		4.0	1				
		5.0	<1				
		6.0	1				
		7.0	<1				
		8.0	<1				
		9.0	1				
10.0	1						

注)網掛けは、基準不適合を示す。