

土壤汚染詳細調査結果(鉛及びその化合物)(溶出量)

単位 区画	地番	採取深度 (GL-m)	溶出量 (mg/L)	単位 区画	地番	採取深度 (GL-m)	溶出量 (mg/L)	単位 区画	地番	採取深度 (GL-m)	溶出量 (mg/L)
A1-3	大阪市東淀川区 下新庄二丁目 443、444 の各一部	0~0.5	0.014	A2-9	大阪市東淀川区 下新庄二丁目 443、444 の各一部	0~0.5	0.017	A4-8	大阪市東淀川区 下新庄二丁目 443、444 の各一部	0~0.5	0.024
		0.6	<0.005			0.6	<0.005			0.6	0.009
		1.0	<0.005			1.0	<0.005			1.0	0.009
		2.0	<0.005			2.0	<0.005			2.0	0.010
		3.0	<0.005			3.0	<0.005			3.0	<0.005
		4.0	<0.005			4.0	<0.005			4.0	<0.005
		5.0	<0.005			5.0	<0.005			5.0	<0.005
		6.0	<0.005			6.0	<0.005			6.0	<0.005
		7.0	<0.005			7.0	<0.005			7.0	<0.005
		8.0	<0.005			8.0	<0.005			8.0	<0.005
		9.0	<0.005			9.0	<0.005			9.0	<0.005
10.0	<0.005	10.0	<0.005	10.0	<0.005						
A1-6	大阪市東淀川区 下新庄二丁目 443、444 の各一部	0~0.5	0.023	A3-3	大阪市東淀川区 下新庄二丁目 443、444 の各一部	0~0.5	0.013	A5-2	大阪市東淀川区 下新庄二丁目 443、444 の各一部	0~0.5	0.014
		0.6	<0.005			0.6	0.027			1.0	0.053
		1.0	<0.005			1.0	0.009			1.5	<0.005
		2.0	<0.005			2.0	<0.005			2.0	<0.005
		3.0	<0.005			3.0	<0.005			3.0	<0.005
		4.0	<0.005			4.0	<0.005			4.0	<0.005
		5.0	<0.005			5.0	<0.005			5.0	<0.005
		6.0	<0.005			6.0	<0.005			6.0	<0.005
		7.0	<0.005			7.0	<0.005			7.0	<0.005
		8.0	<0.005			8.0	<0.005			8.0	<0.005
		9.0	<0.005			9.0	<0.005			9.0	<0.005
10.0	<0.005	10.0	<0.005	10.0	<0.005						
A1-9	大阪市東淀川区 下新庄二丁目 443、444 の各一部	0~0.5	0.013	A3-6	大阪市東淀川区 下新庄二丁目 443、444 の各一部	0~0.5	0.025	A5-5	大阪市東淀川区 下新庄二丁目 443、444 の各一部	0~0.5	0.025
		0.6	<0.005			0.6	0.011			1.0	0.011
		1.0	<0.005			1.0	<0.005			2.0	0.017
		2.0	<0.005			2.0	0.006			2.5	<0.005
		3.0	<0.005			3.0	<0.005			3.0	<0.005
		4.0	<0.005			4.0	<0.005			4.0	<0.005
		5.0	<0.005			5.0	<0.005			5.0	<0.005
		6.0	0.005			6.0	<0.005			6.0	<0.005
		7.0	<0.005			7.0	<0.005			7.0	<0.005
		8.0	<0.005			8.0	<0.005			8.0	<0.005
		9.0	<0.005			9.0	<0.005			9.0	<0.005
10.0	<0.005	10.0	<0.005	10.0	<0.005						
A2-3	大阪市東淀川区 下新庄二丁目 443、444 の各一部	0~0.5	0.012	A4-2	大阪市東淀川区 下新庄二丁目 443、444 の各一部	0~0.5	0.017	A5-8	大阪市東淀川区 下新庄二丁目 443、444 の各一部	0~0.5	0.013
		0.6	0.011			0.6	0.007			1.0	0.048
		1.0	<0.005			1.0	<0.005			2.0	0.086
		2.0	<0.005			2.0	<0.005			2.5	<0.005
		3.0	<0.005			3.0	<0.005			3.0	<0.005
		4.0	<0.005			4.0	<0.005			4.0	<0.005
		5.0	<0.005			5.0	<0.005			5.0	<0.005
		6.0	<0.005			6.0	<0.005			6.0	<0.005
		7.0	<0.005			7.0	<0.005			7.0	<0.005
		8.0	<0.005			8.0	<0.005			8.0	<0.005
		9.0	<0.005			9.0	<0.005			9.0	<0.005
10.0	<0.005	10.0	<0.005	10.0	<0.005						
A2-6	大阪市東淀川区 下新庄二丁目 443、444 の各一部	0~0.5	0.011	A4-5	大阪市東淀川区 下新庄二丁目 443、444 の各一部	0~0.5	0.022	B8-9	大阪市東淀川区 下新庄二丁目 443、444 の各一部	0~0.5	0.012
		0.6	<0.005			0.6	<0.005			1.0	0.018
		1.0	<0.005			1.0	0.005			1.5	<0.005
		2.0	<0.005			2.0	<0.005			2.0	<0.005
		3.0	<0.005			3.0	<0.005			3.0	<0.005
		4.0	<0.005			4.0	<0.005			4.0	<0.005
		5.0	<0.005			5.0	<0.005			5.0	<0.005
		6.0	<0.005			6.0	<0.005			6.0	<0.005
		7.0	<0.005			7.0	<0.005			7.0	<0.005
		8.0	<0.005			8.0	<0.005			8.0	<0.005
		9.0	<0.005			9.0	<0.005			9.0	<0.005
10.0	<0.005	10.0	<0.005	10.0	0.009						
B9-3	大阪市東淀川区 下新庄二丁目 444の一部	0~0.5	0.014							0~0.5	0.014
		1.0	0.019							1.0	0.019
		1.5	<0.005							1.5	<0.005
		2.0	<0.005							2.0	<0.005
		3.0	<0.005							3.0	<0.005
		4.0	<0.005							4.0	<0.005
		5.0	<0.005							5.0	<0.005
		6.0	<0.005							6.0	<0.005
		7.0	<0.005							7.0	<0.005
		8.0	<0.005							8.0	<0.005
		9.0	<0.005							9.0	<0.005
10.0	<0.005							10.0	<0.005		

注) 網掛けは、基準不適合を示す。